

FIG.1




FIG.2




FIG.3




FIG. 4




FIG.5A




FIG.5B




FIG.6




FIG.7




FIG.8A




FIG.8B




FIG.9A

STEP-DOWN SWITCHING




FIG.9B




FIG.10A




FIG.10B




FIG.11





FIG.12A



MEASUREMENT PATTERN

FIG.12B




FIG.13

